

FAST II
RESIN PARTS

1/35
1/20

návod












PHOTO-ETCHED PARTS













FAST II

1/35
4/20





návod




FAST II

1/35
5/20

návod



19 20 17



19 20 18 14



70

70

69

14

70 70



50 50

36

44

44

44

49


36




3

4


A




B



C



D



E




F

3x



G




H





FAST II

**1/35
8/20**

návod















FAST II





1/35
10/20

návod











N

2x




O




2x







P



P










FAST II


1/35
17/20

návod





Configuration for transporting 20-foot containers



Do not use adapters "N" and "O" when transporting flatracks.

